

Radon Test Results 2017

<u>School</u>	<u>Page #</u>
1. Joelton Elementary.....	<u>3-4</u>
2. Madison Middle	<u>5</u>
3. Old Center Elementary	<u>6-7</u>
4. Brick Church Middle	<u>8-9</u>
5. Amqui Elementary.....	<u>10</u>
6. Gateway Elementary.....	<u>11</u>
7. Stratton Elementary.....	<u>12-13</u>
8. Bordeaux Elementary.....	<u>14</u>
9. Gra-mar Middle	<u>15</u>
10. Hattie Cotton Elementary.....	<u>16-17</u>
11. Warner Elementary.....	<u>18</u>
12. Caldwell Elementary.....	<u>19</u>
13. Dalewood Middle	<u>20</u>
14. Stratford High.....	<u>21-22</u>
15. Maplewood High.....	<u>23-24</u>
16. Kirkpatrick Elementary.....	<u>25</u>
17. Tulip Grove Elementary.....	<u>26-27</u>
18. Two Rivers Middle	<u>28</u>
19. Ruby Major Elementary.....	<u>29</u>
20. Napier Elementary.....	<u>30-31</u>
21. Donelson Elementary.....	<u>32-33</u>
22. Dupont Elementary.....	<u>34</u>
23. McGavock High	<u>35</u>
24. Spectrum Academy.....	<u>36</u>
25. Mt View Elementary.....	<u>37-39</u>

26. Thurgood Marshall Middle.....	<u>40-41</u>
27. Johnson Middle.....	<u>42</u>
28. Administration Bldg.....	<u>43-44</u>
29. Fall Hamilton Elementary.....	<u>45-46</u>
30. Glenview Elementary.....	<u>47</u>
31. Cane Ridge Elementary.....	<u>48-49</u>
32. Julia Green Elementary.....	<u>50</u>
33. Robertson Academy.....	<u>51</u>
34. Martin Center	<u>52-53</u>
35. Waverly Belmont.....	<u>54</u>
36. Harris Hillman Elementary.....	<u>55</u>
37. Haywood Elementary.....	<u>56-57</u>
38. West End Middle	<u>58-59</u>
39. Murrell School.....	<u>60</u>
40. Granbery Elementary.....	<u>61-63</u>
41. Churchwell Elementary.....	<u>64</u>
42. Jones Paideia Elementary.....	<u>65-66</u>
43. John Early Middle	<u>67</u>
44. Mckissack Middle	<u>68-70</u>
45. Hull Jackson Elementary.....	<u>71</u>
46. McMurray Middle	<u>72</u>
47. W.A. Bass Middle	<u>73-74</u>
48. Hume Fogg High	<u>75</u>
49. Gower Elementary.....	<u>76-77</u>

Radon test result report for:
JOELTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065454	114	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	3.0 ± 0.5	2017-09-26
7065453	115	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.8 ± 0.4	2017-09-26
7065426	116	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.7 ± 0.5	2017-09-26
7065425	117	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.2 ± 0.4	2017-09-26
7065424	118	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.0 ± 0.3	2017-09-26
7065455	119	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.2 ± 0.4	2017-09-26
7065445	120	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.8 ± 0.3	2017-09-26
7065427	120	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.7 ± 0.3	2017-09-26
7065447	123	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.3 ± 0.4	2017-09-26
7065456	124	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.6 ± 0.4	2017-09-26
7065428	125	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.3 ± 0.4	2017-09-26
7065429	126	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.5 ± 0.4	2017-09-26
7065458	127	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	5.6 ± 0.7	2017-09-26
7065457	128	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	3.6 ± 0.5	2017-09-26
7065432	130	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.6 ± 0.4	2017-09-26
7065433	132	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.7 ± 0.3	2017-09-26
7065434	134	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.4 ± 0.4	2017-09-26
7065435	136	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.4 ± 0.4	2017-09-26
7065436	138	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.6 ± 0.4	2017-09-26
7065440	139	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.8 ± 0.5	2017-09-26
7065439	142	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.7 ± 0.4	2017-09-26
7065437	143	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.5 ± 0.4	2017-09-26
7065438	143	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.9 ± 0.3	2017-09-26
7065441	9999	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	< 0.3	2017-09-26
7065421	9999	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	< 0.3	2017-09-26
7065451	ART	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.1 ± 0.4	2017-09-26
7065449	CAFETERIA	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.3 ± 0.3	2017-09-26
7065450	CAFETERIA	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.2 ± 0.3	2017-09-26
7065442	COMPUTER	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	3.4 ± 0.5	2017-09-26
7065420	LIBRARY	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	3.4 ± 0.5	2017-09-26
7065443	MAIN OFFICE	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	2.2 ± 0.4	2017-09-26
7065448	MUSIC	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.9 ± 0.4	2017-09-26
7065423	PRINCIPLA	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	1.8 ± 0.3	2017-09-26
7065446	TEACHER WORKROOM	2017-09-22 @ 3:00 pm	2017-09-25 @ 8:00 am	5.9 ± 0.7	2017-09-26

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
JOELTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026941	127	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	6.5 ± 0.5	2018-07-13
9026942	128	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	2.8 ± 0.3	2018-07-13
9026940	TEACHER&APOS;S WORKROOM	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	5.0 ± 0.4	2018-07-13

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
MADISON MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217201	11	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217200	114	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217199	114	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217198	115	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217197	120	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	2.2 ± 0.3	2018-07-13
7217196	123	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	2.1 ± 0.3	2018-07-13
7217194	124	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	2.3 ± 0.3	2018-07-13
7217195	127	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	3.1 ± 0.3	2018-07-13
7217193	133	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	4.6 ± 0.3	2018-07-13
7217192	136	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	4.1 ± 0.3	2018-07-13
7217191	145	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217190	146	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13
7217202	BAND ROOM	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	2.3 ± 0.3	2018-07-13
7217203	LIFE SKILLS ROOM	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	1.9 ± 0.3	2018-07-13
7217204	MAIN OFFICE	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	0.6 ± 0.2	2018-07-13
7217207	PRINCIPAL'S OFFICE	2018-07-10 @ 10:00 am	2018-07-12 @ 11:00 am	< 0.3	2018-07-13

Radon test result report for:**OLD CENTER ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065108	11	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065106	12	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065105	13	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065117	15	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.7 ± 0.2	2017-10-11
7065116	17	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	1.9 ± 0.4	2017-10-11
7065115	18	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.6 ± 0.3	2017-10-11
7065112	19	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.9 ± 0.3	2017-10-11
7065114	23	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	5.7 ± 0.8	2017-10-11
7065113	25	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065110	28	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.6 ± 0.3	2017-10-11
7065111	28	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.7 ± 0.3	2017-10-11
7065103	5	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.7 ± 0.3	2017-10-11
7065104	7	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.8 ± 0.2	2017-10-11
7065107	8	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065109	9	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065118	CAFETERIA	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065119	LIBRARY	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	1.1 ± 0.3	2017-10-11
7065120	LIBRARY	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	1.0 ± 0.3	2017-10-11
7065102	OFFICE	2017-10-06 @ 9:00 am	2017-10-09 @ 9:00 am	0.8 ± 0.3	2017-10-11

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

OLD CENTER ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026948	23	2018-07-10 @ 11:00 am	2018-07-12 @ 11:00 am	1.9 ± 0.3	2018-07-13
9026949	23	2018-07-10 @ 11:00 am	2018-07-12 @ 11:00 am	2.2 ± 0.3	2018-07-13
9026947	25	2018-07-10 @ 11:00 am	2018-07-12 @ 11:00 am	1.7 ± 0.3	2018-07-13

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

BRICK CHURCH MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065178	116	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.1 ± 0.3	2017-10-11
7065176	145	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	< 0.3	2017-10-11
7065175	149	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.9 ± 0.4	2017-10-11
7065173	150	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.0 ± 0.4	2017-10-11
7065174	151	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.8 ± 0.4	2017-10-11
7065171	155	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.9 ± 0.6	2017-10-11
7065172	155	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	4.1 ± 0.6	2017-10-11
7065170	156	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.0 ± 0.5	2017-10-11
7065169	158	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.4 ± 0.5	2017-10-11
7065168	159	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.5 ± 0.5	2017-10-11
7065167	162	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.2 ± 0.5	2017-10-11
7065166	163	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.4 ± 0.5	2017-10-11
7065164	165	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.8 ± 0.5	2017-10-11
7065165	166	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.0 ± 0.5	2017-10-11
7065163	171	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.2 ± 0.4	2017-10-11
7065162	174	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.4 ± 0.4	2017-10-11
7065153	176	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.7 ± 0.5	2017-10-11
7065154	179	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	3.2 ± 0.5	2017-10-11
7065155	182	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.7 ± 0.4	2017-10-11
7065156	183	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.7 ± 0.5	2017-10-11
7065158	185	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.6 ± 0.4	2017-10-11
7065157	186	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.4 ± 0.4	2017-10-11
7065159	188	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.9 ± 0.4	2017-10-11
7065160	188	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.8 ± 0.5	2017-10-11
7065152	192	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.4 ± 0.3	2017-10-11
7065150	193	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.8 ± 0.3	2017-10-11
7065151	193	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.8 ± 0.4	2017-10-11
7065149	194	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.6 ± 0.3	2017-10-11
7065148	195	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.9 ± 0.4	2017-10-11
7065181	9999	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	< 0.3	2017-10-11
7065182	9999	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	< 0.3	2017-10-11
7065161	9999	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	< 0.3	2017-10-11
7065177	CAFETERIA	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	0.7 ± 0.3	2017-10-11
7065180	MEDIA CENTER	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.0 ± 0.4	2017-10-11
7065179	MEDIA CENTER	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	2.1 ± 0.4	2017-10-11
7065147	OFFICE	2017-10-06 @ 11:00 am	2017-10-09 @ 12:00 pm	1.4 ± 0.3	2017-10-11

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

BRICK CHURCH ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026946	155	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	3.3 ± 0.3	2018-07-13
9026945	158	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	3.3 ± 0.3	2018-07-13
9026944	159	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	3.0 ± 0.3	2018-07-13
9026943	163	2018-07-10 @ 10:00 am	2018-07-12 @ 10:00 am	2.9 ± 0.3	2018-07-13

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
AMQUI ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065139	102	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.7 ± 0.5	2017-10-11
7065140	102	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	3.3 ± 0.5	2017-10-11
7065138	104	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.2 ± 0.4	2017-10-11
7065137	106	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.4 ± 0.4	2017-10-11
7065136	108	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.9 ± 0.4	2017-10-11
7065135	110	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.9 ± 0.4	2017-10-11
7065134	113	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.7 ± 0.4	2017-10-11
7065133	114	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.9 ± 0.4	2017-10-11
7065132	117	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.3 ± 0.4	2017-10-11
7065130	118	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.4 ± 0.4	2017-10-11
7065131	118	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.9 ± 0.4	2017-10-11
7065128	120	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.3 ± 0.4	2017-10-11
7065127	123	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.0 ± 0.4	2017-10-11
7065126	124	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.0 ± 0.4	2017-10-11
7065125	127	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.4 ± 0.4	2017-10-11
7065124	128	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.2 ± 0.4	2017-10-11
7065144	129	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.9 ± 0.4	2017-10-11
7065123	130	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	1.8 ± 0.4	2017-10-11
7065143	149	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.3 ± 0.4	2017-10-11
7065146	155	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	3.8 ± 0.6	2017-10-11
7065121	9999	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065141	9999	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065145	CAFETERIA	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	3.3 ± 0.5	2017-10-11
7065142	MEDIA CENTER	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.7 ± 0.5	2017-10-11
7065122	OFFICE	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.2 ± 0.4	2017-10-11
7065129	SPEECH	2017-10-06 @ 10:00 am	2017-10-09 @ 10:00 am	2.2 ± 0.4	2017-10-11

Radon test result report for:**GATEWAY ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065708	101	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065709	102	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065710	105	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065711	105	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065707	203	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	2.2 ± 0.4	2017-10-11
7065702	206	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	2.9 ± 0.5	2017-10-11
7065701	300	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	2.7 ± 0.5	2017-10-11
7065703	304	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065704	308	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065706	309	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065713	9999	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	< 0.3	2017-10-11
7065712	GUIDANCE	2017-10-06 @ 9:00 am	2017-10-09 @ 10:00 am	0.6 ± 0.2	2017-10-11

Radon test result report for:
STRATTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962275	106	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	1.7 ± 0.2	2017-12-22
7962272	107	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	1.9 ± 0.2	2017-12-22
7962273	107	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	1.9 ± 0.2	2017-12-22
7962274	111	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	2.5 ± 0.3	2017-12-22
7962276	117	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	1.1 ± 0.2	2017-12-22
7962277	121	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	6.9 ± 0.4	2017-12-22
7962278	122	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	0.8 ± 0.2	2017-12-22
7962279	125	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	0.6 ± 0.2	2017-12-22
7962281	127	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	0.5 ± 0.2	2017-12-22
7962282	127	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-22
7962280	128	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-22
7962284	136	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	0.9 ± 0.2	2017-12-22
7962286	139	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	0.9 ± 0.2	2017-12-22
7962285	142	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-22
7962287	144	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	1.2 ± 0.2	2017-12-22
7962288	145	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-22
7962289	148	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	1.2 ± 0.2	2017-12-22
7962290	152	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	1.8 ± 0.3	2017-12-22
7962291	156	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-22
7962292	159	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	0.9 ± 0.2	2017-12-22
7962293	159	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	1.1 ± 0.2	2017-12-22
7962294	161	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	1.5 ± 0.2	2017-12-22
7962295	163	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	0.5 ± 0.2	2017-12-22
7962296	182	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	3.0 ± 0.3	2017-12-22
7962283	9999	2017-12-18 @ 2:00 pm	2017-12-21 @ 11:00 am	< 0.3	2017-12-26
7962297	GUIDANCE	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	2.8 ± 0.3	2017-12-22
7962298	OFFICE	2017-12-18 @ 3:00 pm	2017-12-21 @ 11:00 am	3.6 ± 0.3	2017-12-22

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

STRATTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217205	117	2018-07-10 @ 11:00 am	2018-07-12 @ 11:00 am	0.7 ± 0.2	2018-07-13
7217206	121	2018-07-10 @ 11:00 am	2018-07-12 @ 11:00 am	0.9 ± 0.2	2018-07-13

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
BORDEAUX ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962401	102	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	0.7 ± 0.4	2017-12-26
7962409	103	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	< 0.3	2017-12-26
7962410	103	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	1.0 ± 0.5	2017-12-26
7962402	104	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	0.7 ± 0.5	2017-12-26
7962403	105	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	< 0.3	2017-12-26
7962408	106	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	< 0.3	2017-12-26
7962407	107	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	1.1 ± 0.4	2017-12-26
7962404	108	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	< 0.3	2017-12-26
7962405	109	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	0.6 ± 0.4	2017-12-26
7962406	CAFETERIA	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	1.4 ± 0.6	2017-12-26
7962411	OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 9:00 am	< 0.3	2017-12-26

Radon test result report for:
GRA-MAR MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217209	115	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.5 ± 0.5	2018-07-17
7217218	130	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.9 ± 0.5	2018-07-17
7217217	131	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	2.0 ± 0.5	2018-07-17
7217216	134	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	2.3 ± 0.5	2018-07-17
7217215	138	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.7 ± 0.5	2018-07-17
7217214	139	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.7 ± 0.5	2018-07-17
7217211	142	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.8 ± 0.5	2018-07-17
7217212	142	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.2 ± 0.5	2018-07-17
7217210	143	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.5 ± 0.5	2018-07-17
7217213	9999	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	< 0.3	2018-07-17
7207421	ART	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.6 ± 0.6	2018-07-17
7217220	BAND ROOM	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	2.8 ± 0.5	2018-07-17
7217208	COMPUTER LAB	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.3 ± 0.4	2018-07-17
7207422	MAIN OFFICE	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.8 ± 0.5	2018-07-17
7207423	PRINCIPAL&APOS;S OFFICE	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	3.8 ± 0.6	2018-07-17
7217219	READING CLINIC	2018-07-10 @ 12:00 pm	2018-07-12 @ 12:00 pm	1.8 ± 0.5	2018-07-17

Radon test result report for:

HATTIE COTTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065714	100	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	4.1 ± 0.6	2017-10-11
7065715	101	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	3.7 ± 0.5	2017-10-11
7065716	103	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	4.4 ± 0.6	2017-10-11
7065718	104	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	3.1 ± 0.5	2017-10-11
7065719	106	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	5.2 ± 0.7	2017-10-11
7065720	106	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	5.5 ± 0.7	2017-10-11
7065722	108	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	9.1 ± 1.1	2017-10-11
7065723	110	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	3.0 ± 0.5	2017-10-11
7065724	111	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	3.7 ± 0.6	2017-10-11
7065721	9999	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11
7065729	ASST. PRINCIPAL	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	5.6 ± 0.7	2017-10-11
7065717	GUIDANCE	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	2.8 ± 0.4	2017-10-11
7065732	INTERVENE OFFICE	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	4.1 ± 0.6	2017-10-11
7065727	LIBRARY	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	4.4 ± 0.6	2017-10-11
7065730	MAIN OFFICE	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	6.1 ± 0.8	2017-10-11
7065731	MAIN OFFICE	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	6.5 ± 0.8	2017-10-11
7065728	MUSIC	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	3.9 ± 0.6	2017-10-11
7065725	PRINCIPAL	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	6.0 ± 0.8	2017-10-11
7065726	VANDERBUILT OFFI	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	4.2 ± 0.6	2017-10-11

Radon test result report for:

HATTIE COTTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217170	100	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.8 ± 0.3	2018-06-28
7217166	101	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	2.0 ± 0.3	2018-06-28
7217169	103	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.8 ± 0.3	2018-06-28
7217167	105	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.9 ± 0.3	2018-06-28
7217168	105	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	2.1 ± 0.3	2018-06-28
7217165	106	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	3.1 ± 0.3	2018-06-28
7217164	107	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	2.3 ± 0.3	2018-06-28
7217161	108	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.9 ± 0.3	2018-06-28
7217163	111	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.0 ± 0.3	2018-06-28
7217162	114	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.5 ± 0.3	2018-06-28
7217176	9999	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	< 0.3	2018-06-28
7217174	ASST. PRINCIPLES	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	4.4 ± 0.4	2018-06-28
7217160	LIBRARY	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	1.8 ± 0.3	2018-06-28
7217171	MAIN OFFICE	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	3.7 ± 0.3	2018-06-28
7217175	MUSIC	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	2.4 ± 0.3	2018-06-28
7217172	PRINCIPLES OFFICE	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	4.4 ± 0.3	2018-06-28
7217173	VANDERBUILT OFFICE	2018-06-25 @ 11:00 am	2018-06-27 @ 12:00 pm	4.4 ± 0.4	2018-06-28

Radon test result report for:**WARNER ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065737	101	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	< 0.3	2017-10-11
7065738	101	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	< 0.3	2017-10-11
7065735	107	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	1.0 ± 0.3	2017-10-11
7065734	110	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	2.8 ± 0.5	2017-10-11
7065733	112	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	1.8 ± 0.3	2017-10-11
7065739	9999	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	< 0.3	2017-10-11
7065736	CAFETERIA	2017-10-06 @ 11:00 am	2017-10-09 @ 2:00 pm	< 0.3	2017-10-11

Radon test result report for:

CALDWELL ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065304	107	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	0.7 ± 0.3	2017-10-11
7065302	109	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11
7065312	124	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11
7065305	142	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	1.2 ± 0.3	2017-10-11
7065309	154	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	1.6 ± 0.3	2017-10-11
7065308	160	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	0.9 ± 0.3	2017-10-11
7065307	161	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	2.7 ± 0.5	2017-10-11
7065306	162	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11
7065303	CAFETERIA	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11
7065310	LIBRARY	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	1.4 ± 0.3	2017-10-11
7065311	LIBRARY	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	0.8 ± 0.3	2017-10-11
7065313	MAIN OFFICE	2017-10-06 @ 10:00 am	2017-10-09 @ 1:00 pm	< 0.3	2017-10-11

Radon test result report for:
DALEWOOD MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065626	105	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	3.2 ± 0.5	2017-10-11
7065625	113	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	3.1 ± 0.5	2017-10-11
7065610	503	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	1.1 ± 0.3	2017-10-11
7065604	507	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.8 ± 0.5	2017-10-11
7065605	508	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	3.4 ± 0.5	2017-10-11
7065606	509	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.8 ± 0.5	2017-10-11
7065619	602	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	1.5 ± 0.4	2017-10-11
7065616	605	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	1.0 ± 0.3	2017-10-11
7065617	607	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	1.0 ± 0.3	2017-10-11
7065618	608	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	1.9 ± 0.4	2017-10-11
7065620	610	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	0.6 ± 0.3	2017-10-11
7065621	610	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	< 0.3	2017-10-11
7065623	611	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	1.2 ± 0.3	2017-10-11
7065613	701	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.7 ± 0.5	2017-10-11
7065614	704	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.3 ± 0.4	2017-10-11
7065615	706	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.2 ± 0.4	2017-10-11
7065611	710	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	3.7 ± 0.6	2017-10-11
7065612	710	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	3.6 ± 0.6	2017-10-11
7065609	713	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.9 ± 0.5	2017-10-11
7065608	714	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	2.8 ± 0.5	2017-10-11
7065607	717	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	1.5 ± 0.4	2017-10-11
7065622	9999	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	< 0.3	2017-10-11
7065601	9999	2017-10-06 @ 3:00 pm	2017-10-09 @ 11:00 am	< 0.3	2017-10-11
7065624	MAIN OFFICE	2017-10-06 @ 4:00 pm	2017-10-09 @ 11:00 am	3.1 ± 0.5	2017-10-11

Radon test result report for:
STRATFORD HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962454	100	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	3.1 ± 0.4	2018-04-06
7962480	1014	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	< 0.3	2018-04-06
7962479	1015	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	0.6 ± 0.2	2018-04-06
7962478	1018	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	1.3 ± 0.3	2018-04-06
7962461	1020	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	1.5 ± 0.3	2018-04-06
7962460	1024	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	< 0.3	2018-04-06
7962455	103	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.3 ± 0.3	2018-04-06
7962459	1036	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.6 ± 0.3	2018-04-06
7962456	104	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	14.0 ± 0.9	2018-04-06
7962462	1043	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	0.8 ± 0.2	2018-04-06
7962463	1043	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	< 0.3	2018-04-06
7962457	105	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	1.8 ± 0.3	2018-04-06
7962458	106	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	3.2 ± 0.4	2018-04-06
7962477	1100	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	3.4 ± 0.4	2018-04-06
7962465	1101	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	1.7 ± 0.3	2018-04-06
7962472	1102	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.2 ± 0.3	2018-04-06
7962473	1102	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.4 ± 0.3	2018-04-06
7962471	1103.1	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.3 ± 0.4	2018-04-06
7962476	1104	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	4.1 ± 0.4	2018-04-06
7962468	1105	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.0 ± 0.4	2018-04-06
7962475	1106	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	4.5 ± 0.4	2018-04-06
7962469	1109.1	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	0.7 ± 0.2	2018-04-06
7962470	1111	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.3 ± 0.3	2018-04-06
7962464	1113	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	2.7 ± 0.4	2018-04-06
7962467	1200	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	1.3 ± 0.3	2018-04-06
7962466	1203	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	< 0.3	2018-04-06
7962474	BLANK	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	< 0.3	2018-04-06
7962481	MAIN OFFICE	2018-04-02 @ 11:00 am	2018-04-04 @ 11:00 am	0.8 ± 0.3	2018-04-06

Radon test result report for:
STRATFORD HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7207383	100	2018-06-11 @ 12:00 pm	2018-06-13 @ 11:00 am	1.9 ± 0.3	2018-06-15
7207382	103	2018-06-11 @ 12:00 pm	2018-06-13 @ 11:00 am	1.0 ± 0.3	2018-06-15
7207381	104	2018-06-11 @ 12:00 pm	2018-06-13 @ 11:00 am	2.8 ± 0.4	2018-06-15
7207379	1104	2018-06-11 @ 12:00 pm	2018-06-13 @ 11:00 am	2.8 ± 0.3	2018-06-15
7207380	1106	2018-06-11 @ 12:00 pm	2018-06-13 @ 11:00 am	1.6 ± 0.3	2018-06-15

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
MAPLEWOOD HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065322	103	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.6 ± 0.4	2017-10-11
7065321	105	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.2 ± 0.3	2017-10-11
7065325	106A	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.5 ± 0.3	2017-10-11
7065324	109	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.2 ± 0.3	2017-10-11
7065326	110	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	0.7 ± 0.3	2017-10-11
7065328	112	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.9 ± 0.4	2017-10-11
7065327	114	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.4 ± 0.3	2017-10-11
7065329	116	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.2 ± 0.3	2017-10-11
7065320	9999	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065323	BANDROOM	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	< 0.3	2017-10-11
7065316	ENROLLMENT CENTE	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	4.1 ± 0.6	2017-10-11
7065314	LL01	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.5 ± 0.3	2017-10-11
7065315	LL02	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.0 ± 0.3	2017-10-11
7065339	MAIN OFFICE	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.1 ± 0.3	2017-10-11
7065338	MAIN OFFICE	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.3 ± 0.3	2017-10-11
7065319	OFFICE-129	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	0.9 ± 0.3	2017-10-11
7065317	STUDENT SERVICES	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.0 ± 0.3	2017-10-11
7065318	STUDENT SERVICES	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	0.6 ± 0.2	2017-10-11
7065330	V 101	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	2.6 ± 0.5	2017-10-11
7065336	V-202A	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	1.4 ± 0.3	2017-10-11
7065335	V-209	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	2.8 ± 0.5	2017-10-11
7065337	V-211 (ROTC)	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	2.7 ± 0.5	2017-10-11
7065331	V101	2017-10-06 @ 12:00 pm	2017-10-09 @ 9:00 am	2.6 ± 0.4	2017-10-11

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
MAPLEWOOD HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026934	ENROLLMENT CENTER	2018-07-03 @ 11:00 am	2018-07-05 @ 11:00 am	3.1 ± 0.3	2018-07-06

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:**KIRPATRICK ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962267	102	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	1.8 ± 0.2	2017-12-22
7962268	103	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	1.5 ± 0.2	2017-12-22
7962269	105	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	1.4 ± 0.2	2017-12-22
7962270	106	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	2.3 ± 0.3	2017-12-22
7962266	110	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	1.0 ± 0.2	2017-12-22
7962265	112	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	0.6 ± 0.2	2017-12-22
7962264	114	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	1.0 ± 0.2	2017-12-22
7962271	FRONT OFFICE	2017-12-18 @ 1:00 pm	2017-12-21 @ 10:00 am	2.7 ± 0.3	2017-12-22

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:**TULIP GROVE ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065459	100	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	3.8 ± 0.6	2017-10-03
7065467	101	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	1.5 ± 0.3	2017-10-03
7065468	101	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.2 ± 0.4	2017-10-03
7065460	102	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	5.0 ± 0.7	2017-10-03
7065462	105	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	3.7 ± 0.5	2017-10-03
7065463	106	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	4.8 ± 0.6	2017-10-03
7065466	109	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.8 ± 0.5	2017-10-03
7065464	110	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	4.1 ± 0.6	2017-10-03
7065465	111	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.9 ± 0.5	2017-10-03
7065470	200	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	1.6 ± 0.3	2017-10-03
7065469	201	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.0 ± 0.4	2017-10-03
7065471	204	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.5 ± 0.4	2017-10-03
7065472	205	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.1 ± 0.4	2017-10-03
7065473	210	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.2 ± 0.4	2017-10-03
7065474	214	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	3.7 ± 0.6	2017-10-03
7065475	215	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	3.4 ± 0.5	2017-10-03
7065476	305	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.1 ± 0.4	2017-10-03
7065478	306	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	< 0.3	2017-10-03
7065477	306	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	1.5 ± 0.3	2017-10-03
7065480	309	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	1.8 ± 0.3	2017-10-03
7065479	310	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	3.3 ± 0.5	2017-10-03
7065481	314	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.5 ± 0.4	2017-10-03
7065482	317	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	1.6 ± 0.3	2017-10-03
7065461	9999	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	< 0.3	2017-10-03
7065483	MAIN OFFICE	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	2.3 ± 0.4	2017-10-03
7065484	PRINCIPAL	2017-09-29 @ 2:00 pm	2017-10-02 @ 8:00 am	4.1 ± 0.6	2017-10-03

Radon test result report for:**TULIP GROVE ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026928	102	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	3.2 ± 0.3	2018-07-06
9026929	106	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	3.0 ± 0.3	2018-07-06
9026931	107	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	3.4 ± 0.3	2018-07-06
9026930	110	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	2.7 ± 0.3	2018-07-06
9026933	MAIN OFFICE	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	1.9 ± 0.3	2018-07-06
9026932	PRINCIPAL&APOS;S OFFICE	2018-07-03 @ 10:00 am	2018-07-05 @ 10:00 am	2.3 ± 0.3	2018-07-06

Radon test result report for:
TWO RIVERS MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065751	102	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065750	105	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065747	109	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065746	110	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065745	121	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065744	124	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065743	126	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065742	129	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065741	130	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065748	CAFETERIA	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065749	CAFETERIA	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065740	CENTERSTONE ROOM	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065754	FRONT OFFICE	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065755	FRONT OFFICE	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065752	LECHNERS ROOM	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065753	MUSIC/GUITAR ROO	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065756	PRINCIPAL	2017-10-10 @ 10:00 am	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17

Radon test result report for:

RUBY MAJOR ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065796	1155	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065486	1166	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065800	1167	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065797	1169	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065798	1169	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065485	1172	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065795	1176	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065791	127	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065790	128	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065789	130	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065788	130	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065787	135	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065786	136	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065491	154	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065490	157	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065489	164	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065488	165	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065799	169	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065487	170	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	1.1 ± 0.4	2017-10-17
7065496	9999	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065493	ASST. PRINCIPAL	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065492	GUIDANCE	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065792	LIBRARY	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065494	MAIN OFFICE	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065495	MAIN OFFICE	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065793	MUSIC	2017-10-10 @ 1:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17

Radon test result report for:
NAPIER ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962501	101	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	9.2 ± 0.5	2017-12-22
7962502	102	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	6.7 ± 0.4	2017-12-22
7962503	105	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	6.4 ± 0.4	2017-12-22
7962504	106	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	6.8 ± 0.4	2017-12-22
7962505	109	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	9.5 ± 0.5	2017-12-22
7962506	110	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	14.1 ± 0.6	2017-12-22
7962507	112	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	14.2 ± 0.6	2017-12-22
7962508	113	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	9.5 ± 0.5	2017-12-22
7962509	114	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	9.1 ± 0.5	2017-12-22
7962510	114	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	10.0 ± 0.5	2017-12-22
7962511	116	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	9.1 ± 0.5	2017-12-22
7962512	119	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	12.9 ± 0.5	2017-12-22
7962513	120	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	5.7 ± 0.3	2017-12-22
7962514	121	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	12.2 ± 0.5	2017-12-22
7962515	122	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	11.0 ± 0.5	2017-12-22
7962516	MAIN OFFICE	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	4.2 ± 0.3	2017-12-22
7962517	PRINCIPAL OFFICE	2017-12-18 @ 1:00 pm	2017-12-21 @ 12:00 pm	4.8 ± 0.3	2017-12-22

Radon test result report for:
NAPIER ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962482	101	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962484	102	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962483	102	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962485	105	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	0.8 ± 0.3	2018-04-06
7962486	106	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	0.9 ± 0.3	2018-04-06
7962487	109	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	0.9 ± 0.3	2018-04-06
7962488	110	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962489	112	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962490	113	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	1.4 ± 0.3	2018-04-06
7962491	114	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962492	116	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962493	119	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	1.1 ± 0.3	2018-04-06
7962495	120	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962497	121	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	1.0 ± 0.3	2018-04-06
7962496	121	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	0.9 ± 0.3	2018-04-06
7962498	122	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	3.8 ± 0.5	2018-04-06
7962494	BLANK	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962499	MAIN OFFICE	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06
7962500	MRS. BUCHANAN	2018-04-02 @ 2:00 pm	2018-04-04 @ 12:00 pm	< 0.3	2018-04-06

Radon test result report for:
DONELSON MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962361	100	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	11.1 ± 0.5	2017-12-20
7962363	104	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	36.6 ± 1.1	2017-12-20
7962362	105	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	10.1 ± 0.5	2017-12-20
7962364	107	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	17.5 ± 0.6	2017-12-20
7962365	109	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	17.3 ± 0.6	2017-12-20
7962372	112	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	10.9 ± 0.5	2017-12-20
7962366	115	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	58.8 ± 1.5	2017-12-20
7962367	117	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	60.4 ± 1.5	2017-12-20
7962368	119	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	83.4 ± 1.9	2017-12-20
7962369	119	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	105.0 ± 2.3	2017-12-20
7962370	120	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	39.1 ± 1.1	2017-12-20
7962375	9999	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	< 0.3	2017-12-20
7962373	MAIN OFFICE	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	14.4 ± 0.6	2017-12-20
7962374	PRINCIPAL	2017-12-15 @ 1:00 pm	2017-12-19 @ 12:00 pm	11.6 ± 0.5	2017-12-20

I2356 / ROAA YOUSIF

Kit Number	Start Date	Start Time	End Date	End Time	Temp.	Facility	Building	Room	Project ID	Floor	Result
9059254	2018-08-31	10:00 am	2018-09-04	7:00 am	73	DONELSON MIDDLE		121		3	2.4
9059255	2018-08-31	10:00 am	2018-09-04	7:00 am	74	DONELSON MIDDLE		117		3	< 0.3
9059256	2018-08-31	10:00 am	2018-09-04	7:00 am	73	DONELSON MIDDLE		118		3	0.8
9059257	2018-08-31	10:00 am	2018-09-04	7:00 am	74	DONELSON MIDDLE		116		3	0.6
9059258	2018-08-31	10:00 am	2018-09-04	7:00 am	73	DONELSON MIDDLE		112		3	< 0.3
9059259	2018-08-31	10:00 am	2018-09-04	7:00 am	74	DONELSON MIDDLE		109		3	< 0.3
9059260	2018-08-31	10:00 am	2018-09-04	7:00 am	71	DONELSON MIDDLE		100		3	0.6
9059261	2018-08-31	10:00 am	2018-09-04	7:00 am	69	DONELSON MIDDLE		105		3	0.7
9059262	2018-08-31	10:00 am	2018-09-04	7:00 am	71	DONELSON MIDDLE		104		3	< 0.3
9059263	2018-08-31	10:00 am	2018-09-04	7:00 am	71	DONELSON MIDDLE		104		3	< 0.3
9059264	2018-08-31	10:00 am	2018-09-04	7:00 am	70	DONELSON MIDDLE		BAND ROOM		3	< 0.3
9059265	2018-08-31	10:00 am	2018-09-04	7:00 am	72	DONELSON MIDDLE		108		3	< 0.3
9059266	2018-08-31	10:00 am	2018-09-04	7:00 am	75	DONELSON MIDDLE		MAIN OFFICE		3	< 0.3
9059267	2018-08-31	10:00 am	2018-09-04	7:00 am	70	DONELSON MIDDLE		PRINCIPAL&APOS;S OFFICE		3	< 0.3

Radon test result report for:
DUPONT ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065767	1	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.9 ± 0.5	2017-10-17
7065757	11	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	2.8 ± 0.6	2017-10-17
7065758	11	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	3.4 ± 0.6	2017-10-17
7065761	12	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065774	13	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	1.6 ± 0.4	2017-10-17
7065775	17	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	0.9 ± 0.3	2017-10-17
7065766	2	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.8 ± 0.4	2017-10-17
7065777	22	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065778	22	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065780	23	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	0.6 ± 0.3	2017-10-17
7065781	25	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065765	3	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.9 ± 0.5	2017-10-17
7065772	30	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	1.9 ± 0.4	2017-10-17
7065771	33	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	2.8 ± 0.5	2017-10-17
7065764	5	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.0 ± 0.4	2017-10-17
7065763	6	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.1 ± 0.4	2017-10-17
7065782	8	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	1.7 ± 0.4	2017-10-17
7065783	9	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	2.2 ± 0.5	2017-10-17
7065779	9999	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065760	9999	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	< 0.3	2017-10-17
7065768	CAFETERIA	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	2.4 ± 0.5	2017-10-17
7065769	CAFETERIA	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	2.6 ± 0.5	2017-10-17
7065776	COMPUTER LAB	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	0.7 ± 0.3	2017-10-17
7065762	LIBRARY	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	2.4 ± 0.5	2017-10-17
7065784	MAIN OFFICE	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	1.8 ± 0.4	2017-10-17
7065770	MUSIC ROOM	2017-10-10 @ 11:00 am	2017-10-13 @ 1:00 pm	1.8 ± 0.5	2017-10-17
7065785	PRINCIPAL	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	2.3 ± 0.5	2017-10-17
7065773	SCIENCE LAB	2017-10-10 @ 12:00 pm	2017-10-13 @ 1:00 pm	1.4 ± 0.4	2017-10-17

Radon test result report for:
MCGAVOCK HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962327	101	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	1.3 ± 0.2	2017-12-20
7962326	104	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	1.2 ± 0.2	2017-12-20
7962331	108	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962332	109	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962306	114	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962307	114	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.9 ± 0.2	2017-12-20
7962308	117	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	2.4 ± 0.3	2017-12-20
7962310	119	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962309	119	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962311	121	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.9 ± 0.2	2017-12-20
7962313	124	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.9 ± 0.2	2017-12-20
7962314	127	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962316	140	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962317	142	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962318	147	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962319	147	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962321	151	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962322	152	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962325	159	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962304	160	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962302	169	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962303	173	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962320	9999	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962323	ART B	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962330	CENTRAL OFFICE	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	< 0.3	2017-12-20
7962329	CENTRAL OFFICE	2017-12-14 @ 12:00 pm	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20
7962315	MAIN BAND ROOM	2017-12-14 @ 11:00 am	2017-12-18 @ 8:00 am	0.5 ± 0.2	2017-12-20

Radon test result report for:
SPECTRUM ACADEMY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065183	103	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	2.8 ± 0.6	2017-10-17
7065184	108	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	< 0.3	2017-10-17
7065186	113	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065187	115B	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	3.4 ± 0.7	2017-10-17
7065185	LIBRARY	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	2.2 ± 0.5	2017-10-17
7065188	MAIN OFFICE	2017-10-10 @ 10:00 am	2017-10-13 @ 10:00 am	3.7 ± 0.7	2017-10-17

Radon test result report for:
MT. VIEW ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065214	1	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	4.1 ± 0.7	2017-10-17
7065220	10	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	5.0 ± 0.8	2017-10-17
7065221	10	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	4.4 ± 0.7	2017-10-17
7065189	101	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.6 ± 0.4	2017-10-17
7065190	102	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	3.3 ± 0.6	2017-10-17
7065191	106	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.3 ± 0.4	2017-10-17
7065192	106	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065195	107	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.2 ± 0.4	2017-10-17
7065193	108	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065205	109	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	0.9 ± 0.4	2017-10-17
7065219	11	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	4.4 ± 0.7	2017-10-17
7065204	112	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.0 ± 0.4	2017-10-17
7065207	114	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065206	115	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.5 ± 0.4	2017-10-17
7065210	118	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.5 ± 0.4	2017-10-17
7065212	119	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	0.8 ± 0.3	2017-10-17
7065211	119	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065208	121	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.2 ± 0.4	2017-10-17
7065209	124	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.7 ± 0.4	2017-10-17
7065223	13	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	4.1 ± 0.7	2017-10-17
7065224	16	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	6.2 ± 0.9	2017-10-17
7065215	4	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	3.9 ± 0.7	2017-10-17
7065216	6	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	3.1 ± 0.6	2017-10-17
7065217	7	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	3.4 ± 0.6	2017-10-17
7065202	9999	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	< 0.3	2017-10-17
7065222	9999	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	< 0.3	2017-10-17
7065200	ART A	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	0.8 ± 0.3	2017-10-17
7065201	ART A	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	0.9 ± 0.4	2017-10-17
7065198	COMPUTER LAB	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.4 ± 0.4	2017-10-17
7065213	GUIDANCE	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	0.8 ± 0.4	2017-10-17
7065196	LIBRARY	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.5 ± 0.4	2017-10-17
7065225	MAIN OFFICE	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065199	MUSIC A	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.1 ± 0.4	2017-10-17
7065194	RESOURCE ROOM A	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.5 ± 0.4	2017-10-17
7065197	SPEECH ROOM	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	1.2 ± 0.4	2017-10-17
7065218	SUPPORT B	2017-10-10 @ 11:00 am	2017-10-13 @ 10:00 am	5.6 ± 0.8	2017-10-17

Radon test result report for:
MT. VIEW ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7207385	1	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.4 ± 0.4	2018-06-26
7207390	10	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.3 ± 0.4	2018-06-26
7207384	102	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.7 ± 0.4	2018-06-26
7207391	11	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.4 ± 0.4	2018-06-26
7207392	13	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	0.8 ± 0.3	2018-06-26
7207393	16	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.0 ± 0.3	2018-06-26
7207386	4	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.0 ± 0.3	2018-06-26
7207387	6	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.4 ± 0.3	2018-06-26
7207388	7	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.1 ± 0.3	2018-06-26
7207389	SUPPORT B	2018-06-20 @ 12:00 pm	2018-06-22 @ 12:00 pm	1.2 ± 0.3	2018-06-26

Radon test result report for:

THURGOOD MARSHALL MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065226	102	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	9.4 ± 1.2	2017-10-17
7065227	103	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	6.8 ± 0.9	2017-10-17
7065231	111	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	3.7 ± 0.6	2017-10-17
7065232	111	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	4.0 ± 0.7	2017-10-17
7065230	112	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	9.9 ± 1.3	2017-10-17
7065229	114	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	8.9 ± 1.1	2017-10-17
7065233	116	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	3.6 ± 0.6	2017-10-17
7065243	119	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065240	122	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	1.6 ± 0.4	2017-10-17
7065241	122	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	1.7 ± 0.4	2017-10-17
7065244	124	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	1.1 ± 0.3	2017-10-17
7065245	125	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	0.7 ± 0.3	2017-10-17
7065246	127	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	0.7 ± 0.3	2017-10-17
7065247	130	2017-10-10 @ 1:00 pm	2017-10-13 @ 11:00 am	3.0 ± 0.6	2017-10-17
7065235	132	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	1.5 ± 0.4	2017-10-17
7065234	135	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	2.6 ± 0.5	2017-10-17
7065237	137	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	2.6 ± 0.5	2017-10-17
7065236	138	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	4.2 ± 0.7	2017-10-17
7065239	141	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	1.6 ± 0.4	2017-10-17
7065238	142	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	15.1 ± 1.8	2017-10-17
7065242	9999	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065248	ASST. PRINCIPAL	2017-10-10 @ 1:00 pm	2017-10-13 @ 11:00 am	8.6 ± 1.1	2017-10-17
7065228	LIBRARY	2017-10-10 @ 12:00 pm	2017-10-13 @ 11:00 am	6.7 ± 0.9	2017-10-17
7065250	MAIN OFFICE	2017-10-10 @ 1:00 pm	2017-10-13 @ 11:00 am	5.8 ± 0.8	2017-10-17
7065249	PRINCIPAL	2017-10-10 @ 1:00 pm	2017-10-13 @ 11:00 am	11.0 ± 1.4	2017-10-17

Radon test result report for:
THURGOOD MARSHALL

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026917	102	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	11.8 ± 0.6	2018-06-28
9026918	103	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	3.6 ± 0.4	2018-06-28
9026922	111	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	1.7 ± 0.3	2018-06-28
9026921	112	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	1.2 ± 0.2	2018-06-28
9026923	114	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	4.5 ± 0.4	2018-06-28
9026924	142	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	12.2 ± 0.7	2018-06-28
9026926	ASST. PRINCIPAL	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	5.7 ± 0.5	2018-06-28
9026919	LIBRARY	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	1.0 ± 0.2	2018-06-28
9026920	LIBRARY	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	1.3 ± 0.2	2018-06-28
9026925	MAIN OFFICE	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	2.7 ± 0.3	2018-06-28
9026927	PRINCIPAL OFFICE	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	2.5 ± 0.3	2018-06-28

Radon test result report for:**THURGOOD MARSHALL MIDDLE**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9127560	102	2019-01-02 @ 8:00 am	2019-01-04 @ 10:00 am	6.7 ± 0.5	2019-01-08
9127561	104	2019-01-02 @ 8:00 am	2019-01-04 @ 9:00 am	10.0 ± 0.7	2019-01-08
9127558	114	2019-01-02 @ 8:00 am	2019-01-04 @ 9:00 am	8.5 ± 0.7	2019-01-08
9127559	142	2019-01-02 @ 8:00 am	2019-01-04 @ 9:00 am	1.2 ± 0.4	2019-01-08
9127557	ASST. PRINCIPAL&APOS;S	2019-01-02 @ 8:00 am	2019-01-04 @ 9:00 am	10.7 ± 0.8	2019-01-08

Radon test result report for:
JOHNSON MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065341	101	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065342	102	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	1.2 ± 0.4	2017-10-16
7065343	103	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065344	104	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	1.0 ± 0.4	2017-10-16
7065345	202	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065348	203	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065349	203	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065350	205	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065351	207	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	1.0 ± 0.4	2017-10-16
7065352	209	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	0.7 ± 0.4	2017-10-16
7065346	MAIN OFFICE	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	< 0.3	2017-10-16
7065347	PRINCIPAL	2017-10-10 @ 10:00 am	2017-10-12 @ 10:00 am	1.0 ± 0.4	2017-10-16

Radon test result report for:

ADMINISTRARION BUILDING

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962520	9999	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	< 0.3	2017-12-26
7962523	A 112 B	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	5.6 ± 0.4	2017-12-22
7962522	B212	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	3.3 ± 0.3	2017-12-22
7962526	BOBBYE BURGE	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	5.3 ± 0.3	2017-12-22
7962525	BUSINESS CENTER	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	3.9 ± 0.3	2017-12-22
7962527	CRYSTAL ALC PLER	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	4.3 ± 0.3	2017-12-22
7962521	ESS	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	5.6 ± 0.4	2017-12-22
7962531	LAST ROOM ON RIG	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	5.0 ± 0.4	2017-12-22
7962530	OFFICE OF NUTRIT	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	5.5 ± 0.4	2017-12-22
7962529	OFFICE OF NUTRIT	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	6.1 ± 0.4	2017-12-22
7962524	TAMEKA MCDONALD	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	4.3 ± 0.3	2017-12-22
7962518	TERESA STOKES RO	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	6.7 ± 0.4	2017-12-22
7962519	TERESA STOKES RO	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	6.4 ± 0.4	2017-12-22
7962528	TERRY HALL	2017-12-18 @ 2:00 pm	2017-12-21 @ 12:00 pm	4.4 ± 0.3	2017-12-22

Radon test result report for:
ADMINISTRATION BLDG

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026910	A112 B	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.7 ± 0.3	2018-06-28
9026911	A112 B	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.4 ± 0.3	2018-06-28
9026901	B 2121	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.4 ± 0.3	2018-06-28
9026909	CRYSTAL ALC PLER	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.0 ± 0.3	2018-06-28
9026907	ESS	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	4.6 ± 0.4	2018-06-28
9026903	LAST ON THE RIGHT	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.3 ± 0.3	2018-06-28
9026904	OFFICE OF NUTRITIA	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.2 ± 0.3	2018-06-28
9026902	TAMEKA MCDONALD	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	1.9 ± 0.3	2018-06-28
9026906	TERESA STOKES	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	3.7 ± 0.3	2018-06-28
9026905	TERRY HALE	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.4 ± 0.3	2018-06-28
9026908	TISA BEARD	2018-06-25 @ 10:00 am	2018-06-27 @ 1:00 pm	2.4 ± 0.3	2018-06-28

Radon test result report for:

FALL HAMILTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065366	100	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	1.4 ± 0.5	2017-10-16
7065367	101	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	0.8 ± 0.3	2017-10-16
7065369	102	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	1.6 ± 0.5	2017-10-16
7065368	102	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	2.2 ± 0.5	2017-10-16
7065362	207	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	6.0 ± 0.9	2017-10-16
7065361	211	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	4.1 ± 0.7	2017-10-16
7065358	310	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	0.8 ± 0.4	2017-10-16
7065357	310	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	0.9 ± 0.4	2017-10-16
7065356	311	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	0.7 ± 0.4	2017-10-16
7065355	312	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	< 0.3	2017-10-16
7065354	314	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	0.9 ± 0.4	2017-10-16
7065360	316	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	1.5 ± 0.5	2017-10-16
7065353	318	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	1.8 ± 0.5	2017-10-16
7065359	9999	2017-10-10 @ 10:00 am	2017-10-12 @ 11:00 am	< 0.3	2017-10-16
7065364	CENTRAL ALUMNI	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	3.7 ± 0.7	2017-10-16
7065365	CENTRAL ALUMNI	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	3.6 ± 0.7	2017-10-16
7065370	FRONT OFFICE	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	2.9 ± 0.6	2017-10-16
7065371	PRINCIPAL	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	3.4 ± 0.7	2017-10-16
7065363	TEACHER LOUNAGE	2017-10-10 @ 11:00 am	2017-10-12 @ 11:00 am	5.0 ± 0.8	2017-10-16

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

FALL HAMILTON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026938	207	2018-07-03 @ 11:00 am	2018-07-05 @ 11:00 am	6.0 ± 0.4	2018-07-06
9026937	211	2018-07-03 @ 11:00 am	2018-07-05 @ 11:00 am	4.9 ± 0.4	2018-07-06
9026936	TEACHERS LOUNGE	2018-07-03 @ 11:00 am	2018-07-05 @ 11:00 am	6.2 ± 0.4	2018-07-06

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

GLENVIEW ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065372	1	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065397	108	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065398	108	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065400	109	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065385	12	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065384	15	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065383	16	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065382	19	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065381	20	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065395	201	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065394	204	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065386	206	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065380	21	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065387	210	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065388	211	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065389	211	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065390	214	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065391	215	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065392	217	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065377	22	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065378	22	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065393	221	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065376	25	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065375	26	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065373	4	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065374	5	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065379	9999	2017-10-10 @ 12:00 pm	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065399	9999	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065396	LIBRARY	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065629	MAIN OFFICE	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16
7065628	PRINCIPAL	2017-10-10 @ 1:00 am	2017-10-12 @ 1:00 pm	< 0.3	2017-10-16

Radon test result report for:
CANE RIDGE HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962344	1000	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.1 ± 0.2	2017-12-20
7962343	1003	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.1 ± 0.2	2017-12-20
7962340	1007	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	4.1 ± 0.3	2017-12-20
7962356	1100	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.7 ± 0.2	2017-12-20
7962355	1103	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.6 ± 0.2	2017-12-20
7962354	1106	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	3.4 ± 0.3	2017-12-20
7962353	1107	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.8 ± 0.3	2017-12-20
7962352	1109	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.3 ± 0.2	2017-12-20
7962351	1112	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	14.6 ± 0.6	2017-12-20
7962349	1115	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	16.6 ± 0.6	2017-12-20
7962350	1115	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	17.3 ± 0.7	2017-12-20
7962348	1202	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	< 0.3	2017-12-20
7962347	1207	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	0.9 ± 0.2	2017-12-20
7962346	1210	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.4 ± 0.2	2017-12-20
7962345	1215	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.5 ± 0.2	2017-12-20
7962337	1303	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.3 ± 0.2	2017-12-20
7962338	1304	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.2 ± 0.2	2017-12-20
7962339	1304	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.1 ± 0.2	2017-12-20
7962336	1307	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	3.4 ± 0.3	2017-12-20
7962334	1401	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	3.0 ± 0.3	2017-12-20
7962335	1404	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	1.9 ± 0.2	2017-12-20
7962341	9999	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	< 0.3	2017-12-20
7962360	9999	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	< 0.3	2017-12-20
7962357	MAIN OFFICE	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.3 ± 0.2	2017-12-20
7962358	PRINCIPAL	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.0 ± 0.2	2017-12-20
7962359	PRINCIPAL	2017-12-15 @ 10:00 am	2017-12-19 @ 9:00 am	2.3 ± 0.2	2017-12-20

Radon test result report for:
CANE RIDGE HIGH

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7207378	1005	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	0.8 ± 0.3	2018-06-15
7207377	1007	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	0.8 ± 0.3	2018-06-15
7207376	1103	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	< 0.3	2018-06-15
7207373	1110	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	0.6 ± 0.2	2018-06-15
7207372	1112	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	0.6 ± 0.3	2018-06-15
7207374	1114	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	0.8 ± 0.2	2018-06-15
7207375	1115	2018-06-11 @ 11:00 am	2018-06-13 @ 11:00 am	< 0.3	2018-06-15

Radon test result report for:**JULIA GREEN ELEMENTARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962603	1	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	< 0.3	2017-12-26
7962606	11	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.9 ± 0.4	2017-12-26
7962607	12	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.9 ± 0.3	2017-12-26
7962608	14	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	< 0.3	2017-12-26
7962611	17	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.6 ± 0.4	2017-12-26
7962610	18	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.7 ± 0.4	2017-12-26
7962609	18	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.8 ± 0.4	2017-12-26
7962602	2	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	< 0.3	2017-12-26
7962612	21	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	3.0 ± 0.5	2017-12-26
7962613	23	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	3.9 ± 0.5	2017-12-26
7962614	27	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	3.3 ± 0.5	2017-12-26
7962615	31	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	3.3 ± 0.5	2017-12-26
7962616	37	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.7 ± 0.4	2017-12-26
7962617	39	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	2.4 ± 0.4	2017-12-26
7962618	39	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	2.6 ± 0.5	2017-12-26
7962604	5	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.8 ± 0.4	2017-12-26
7962605	6	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	1.4 ± 0.4	2017-12-26
7962619	9999	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	< 0.3	2017-12-26
7962601	OFFICE	2017-12-18 @ 2:00 pm	2017-12-21 @ 1:00 pm	0.8 ± 0.3	2017-12-26

Radon test result report for:
ROBERSTON

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962621	1	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	2.1 ± 0.4	2017-12-26
7962624	2	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	2.0 ± 0.5	2017-12-26
7962625	4	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	1.2 ± 0.4	2017-12-26
7962626	6	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	0.7 ± 0.4	2017-12-26
7962628	7	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	2.6 ± 0.5	2017-12-26
7962629	7	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	3.0 ± 0.5	2017-12-26
7962627	8	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	1.6 ± 0.5	2017-12-26
7962622	9999	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	< 0.3	2017-12-26
7962630	ENROLLMENT	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	0.9 ± 0.4	2017-12-26
7962620	OFFICE	2017-12-18 @ 2:00 pm	2017-12-21 @ 2:00 pm	2.0 ± 0.4	2017-12-26

Radon test result report for:
MARTIN CENTER

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065639	B114	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	0.7 ± 0.4	2017-10-17
7065632	CLASSROOM 2	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	5.2 ± 0.9	2017-10-17
7065633	CLASSROOM 3	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	3.7 ± 0.7	2017-10-17
7065635	CONFERENCE ROOM	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	1.4 ± 0.4	2017-10-17
7065296	LEADERSHIP TEAM	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	3.1 ± 0.6	2017-10-17
7065634	MAIN OFFICE	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	1.6 ± 0.5	2017-10-17
7065636	OFFICE 110	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	1.3 ± 0.4	2017-10-17
7065637	OFFICE 112	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	0.7 ± 0.4	2017-10-17
7065638	OFFICE 112	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	1.2 ± 0.4	2017-10-17
7065297	PERFORMING ARTS	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	< 0.3	2017-10-17
7065298	TECH 1	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	11.8 ± 1.5	2017-10-17
7065631	TECH 3	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	15.3 ± 1.8	2017-10-17
7065300	TECH 3	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	9.5 ± 1.2	2017-10-17
7065299	TECH 4	2017-10-11 @ 12:00 pm	2017-10-13 @ 12:00 pm	12.1 ± 1.5	2017-10-17

Radon test result report for:
MARTIN CENTER

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9026913	9999	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	< 0.3	2018-06-28
9026912	CLASS ROOM 1	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	1.0 ± 0.2	2018-06-28
9026914	TECH LAB 1	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	3.8 ± 0.3	2018-06-28
9026915	TECH LAB 3	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	3.2 ± 0.3	2018-06-28
9026916	TECH LAB 4	2018-06-25 @ 11:00 am	2018-06-27 @ 1:00 pm	4.9 ± 0.4	2018-06-28

Radon test result report for:
WAVERLY BELMONT

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962532	102	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	0.6 ± 0.2	2017-12-22
7962536	108	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	2.4 ± 0.3	2017-12-22
7962535	111	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.6 ± 0.2	2017-12-22
7962537	112	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.0 ± 0.2	2017-12-22
7962539	113	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.5 ± 0.2	2017-12-22
7962538	CAFETERIA	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	< 0.3	2017-12-22
7962534	CLINIC- 107	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.9 ± 0.2	2017-12-22
7962533	MAIN OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.4 ± 0.2	2017-12-22
7962540	PRINCIPAL OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.8 ± 0.2	2017-12-22
7962541	PRINCIPAL OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 12:00 pm	1.6 ± 0.2	2017-12-22

Radon test result report for:

HARRIS HILLMAN ELEMENATRY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065286	16	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065285	18	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	0.6 ± 0.3	2017-10-17
7065281	2	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065288	22	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065289	22	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	0.8 ± 0.3	2017-10-17
7065287	24	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065292	27	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065291	29	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065279	4	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065280	4	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065283	7	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065282	9	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065290	9999	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065284	COMPUTER LAB	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065278	LIBRARY	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065294	MAIN OFFICE	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065295	PRINCIPAL	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17
7065293	WIGGLE ROOM	2017-10-11 @ 11:00 am	2017-10-13 @ 11:00 am	< 0.3	2017-10-17

Radon test result report for:

HAYWOOD ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962559	1	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	10.2 ± 0.5	2017-12-22
7962568	102	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	5.5 ± 0.4	2017-12-22
7962569	105	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	13.0 ± 0.6	2017-12-22
7962570	105	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	12.8 ± 0.6	2017-12-22
7962572	109	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	3.6 ± 0.3	2017-12-22
7962563	11	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	12.0 ± 0.6	2017-12-22
7962574	113	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	5.0 ± 0.3	2017-12-22
7962575	132	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	2.4 ± 0.3	2017-12-22
7962576	136	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	2.8 ± 0.3	2017-12-22
7962564	16	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	7.4 ± 0.4	2017-12-22
7962565	17	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	12.2 ± 0.6	2017-12-22
7962566	21	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	10.4 ± 0.5	2017-12-22
7962567	24	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	2.1 ± 0.2	2017-12-22
7962555	3	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	5.0 ± 0.4	2017-12-22
7962577	30	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	1.3 ± 0.2	2017-12-22
7962578	34	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	14.8 ± 0.6	2017-12-22
7962556	4	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	6.7 ± 0.4	2017-12-22
7962557	7	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	11.1 ± 0.5	2017-12-22
7962558	8	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	9.0 ± 0.5	2017-12-22
7962571	9999	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	< 0.3	2017-12-26
7962561	CAFETERIA	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	4.3 ± 0.3	2017-12-22
7962560	CAFETERIA	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	5.5 ± 0.4	2017-12-22
7962562	COMPUTER LAB	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	8.2 ± 0.4	2017-12-22
7962573	LIBRARY	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	4.9 ± 0.4	2017-12-22
7962579	MAIN OFFICE	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	7.5 ± 0.4	2017-12-22

Radon test result report for:

HAYWOOD ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7207394	1	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	< 0.3	2018-06-26
7207408	102	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.5 ± 0.4	2018-06-26
7207410	103	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.6 ± 0.4	2018-06-26
7207409	105	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.3 ± 0.4	2018-06-26
7207411	109	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.2 ± 0.4	2018-06-26
7207401	11	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	2.9 ± 0.5	2018-06-26
7207413	113	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.8 ± 0.4	2018-06-26
7207402	14A	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.9 ± 0.4	2018-06-26
7207403	17	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.8 ± 0.4	2018-06-26
7207404	20	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.7 ± 0.4	2018-06-26
7207405	21	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.9 ± 0.4	2018-06-26
7207407	24	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.6 ± 0.4	2018-06-26
7207395	3	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	< 0.3	2018-06-26
7207414	30	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.8 ± 0.4	2018-06-26
7207415	34	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	2.1 ± 0.4	2018-06-26
7207416	35	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	2.7 ± 0.5	2018-06-26
7207396	4	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.7 ± 0.3	2018-06-26
7207397	7	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	< 0.3	2018-06-26
7207398	8	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.5 ± 0.3	2018-06-26
7207406	9999	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	< 0.3	2018-06-28
7207400	CAFETERIA	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.7 ± 0.4	2018-06-26
7207399	CAFETERIA	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.9 ± 0.4	2018-06-26
7207417	CAMPUTER LAB	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	0.9 ± 0.4	2018-06-26
7207412	LIBRARY	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	1.7 ± 0.5	2018-06-26
7207418	MAIN OFFICE	2018-06-20 @ 1:00 pm	2018-06-22 @ 1:00 pm	< 0.3	2018-06-26

Radon test result report for:
WEST END MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962542	1	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	1.9 ± 0.3	2017-12-22
7962552	101	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	2.7 ± 0.3	2017-12-22
7962549	102	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	1.6 ± 0.2	2017-12-22
7962550	102	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	1.6 ± 0.3	2017-12-22
7962548	104	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	2.4 ± 0.3	2017-12-22
7962547	105	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	3.3 ± 0.3	2017-12-22
7962545	112	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	8.6 ± 0.5	2017-12-22
7962544	113	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	0.6 ± 0.2	2017-12-22
7962543	2	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	6.0 ± 0.4	2017-12-22
7962546	MAIN OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 1:00 pm	4.4 ± 0.3	2017-12-22
7962554	NURSE	2017-12-19 @ 11:00 am	2017-12-21 @ 1:00 pm	4.0 ± 0.4	2017-12-22

Radon test result report for:
WEST END MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217152	1	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	< 0.3	2018-06-28
7217151	112	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	< 0.3	2018-06-28
7217149	MAIN OFFICE	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	< 0.3	2018-06-28
7217150	NURSE	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	0.8 ± 0.2	2018-06-28

Radon test result report for:
MURRELL SCHOOL

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962635	10	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	2.2 ± 0.3	2017-12-22
7962634	12	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	1.0 ± 0.2	2017-12-22
7962633	13	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	1.0 ± 0.3	2017-12-22
7962632	16	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	1.3 ± 0.2	2017-12-22
7962631	17	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	???? XI	2017-12-22
7962636	CAFETERIA	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	2.3 ± 0.3	2017-12-22
7962637	OFFICE	2017-12-19 @ 10:00 am	2017-12-21 @ 2:00 pm	2.8 ± 0.3	2017-12-22

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
GRANBERY ELEMENTRAY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065271	103	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	4.1 ± 0.7	2017-10-17
7065272	104	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	3.4 ± 0.6	2017-10-17
7065273	107	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	5.5 ± 0.8	2017-10-17
7065274	108	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	3.3 ± 0.6	2017-10-17
7065275	111	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	1.9 ± 0.5	2017-10-17
7065252	113	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	1.7 ± 0.4	2017-10-17
7065251	114	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	2.1 ± 0.5	2017-10-17
7065266	116	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	8.3 ± 1.2	2017-10-17
7065265	119	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	6.3 ± 0.9	2017-10-17
7065264	121	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	6.5 ± 1.0	2017-10-17
7065263	123	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	1.9 ± 0.5	2017-10-17
7065262	124	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	5.4 ± 0.9	2017-10-17
7065260	129	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	4.6 ± 0.8	2017-10-17
7065259	129	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	5.1 ± 0.8	2017-10-17
7065258	132	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	4.3 ± 0.7	2017-10-17
7065267	135	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	5.2 ± 0.8	2017-10-17
7065261	140	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	0.9 ± 0.4	2017-10-17
7065257	145	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	1.2 ± 0.4	2017-10-17
7065256	148	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	0.8 ± 0.4	2017-10-17
7065255	149	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	0.8 ± 0.4	2017-10-17
7065254	155	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	2.3 ± 0.5	2017-10-17
7065253	156	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	0.7 ± 0.4	2017-10-17
7065270	9999	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	< 0.3	2017-10-17
7065268	LIBRARY	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	5.9 ± 0.9	2017-10-17
7065269	LIBRARY	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	4.9 ± 0.8	2017-10-17
7065277	MAIN OFFICE	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	3.6 ± 0.7	2017-10-17
7065276	PRINCIPAL	2017-10-11 @ 10:00 am	2017-10-13 @ 10:00 am	11.5 ± 1.5	2017-10-17

I2356 / ROAA YOUSIF

Kit Number	Start Date	Start Time	End Date	End Time	Temp.	Facility	Building	Room	Project ID	Floor	Result
9088401	2018-11-16	3:00 pm	2018-11-19	8:00 am	71	GRANBERY ELEMENTARY		103		3	3.6
9088402	2018-11-16	3:00 pm	2018-11-19	8:00 am	70	GRANBERY ELEMENTARY		104		3	2.6
9088403	2018-11-16	3:00 pm	2018-11-19	8:00 am	72	GRANBERY ELEMENTARY		107		3	5.9
9088404	2018-11-16	3:00 pm	2018-11-19	8:00 am	69	GRANBERY ELEMENTARY		108		3	2.1
9088405	2018-11-16	3:00 pm	2018-11-19	8:00 am	69	GRANBERY ELEMENTARY		111		3	1.5
9088406	2018-11-16	3:00 pm	2018-11-19	8:00 am	69	GRANBERY ELEMENTARY		155		3	0.6
9088407	2018-11-16	3:00 pm	2018-11-19	8:00 am	69	GRANBERY ELEMENTARY		156		3	1.0
9088408	2018-11-16	3:00 pm	2018-11-19	8:00 am	69	GRANBERY ELEMENTARY		113		3	1.2
9088409	2018-11-16	3:00 pm	2018-11-19	8:00 am	72	GRANBERY ELEMENTARY		114		3	1.5
9088410	2018-11-16	3:00 pm	2018-11-19	8:00 am	72	GRANBERY ELEMENTARY		114		3	1.7
9088411	2018-11-16	3:00 pm	2018-11-19	8:00 am	71	GRANBERY ELEMENTARY		149		3	1.1
9088412	2018-11-16	3:00 pm	2018-11-19	8:00 am	70	GRANBERY ELEMENTARY		148		3	1.5
9088413	2018-11-16	3:00 pm	2018-11-19	8:00 am	68	GRANBERY ELEMENTARY		145		3	1.1
9088414	2018-11-16	3:00 pm	2018-11-19	8:00 am	74	GRANBERY ELEMENTARY		132		3	1.8
9088415	2018-11-16	3:00 pm	2018-11-19	8:00 am	73	GRANBERY ELEMENTARY		129		3	2.8
9088416	2018-11-16	3:00 pm	2018-11-19	8:00 am	75	GRANBERY ELEMENTARY		LIBRARY		3	2.1
9088417	2018-11-16	3:00 pm	2018-11-19	8:00 am	68	GRANBERY ELEMENTARY		140		3	1.2
9088418	2018-11-16	3:00 pm	2018-11-19	8:00 am	73	GRANBERY ELEMENTARY		125		3	4.0
9088419	2018-11-16	3:00 pm	2018-11-19	8:00 am	70	GRANBERY ELEMENTARY		9999		3	< 0.3
9088420	2018-11-16	3:00 pm	2018-11-19	8:00 am	72	GRANBERY ELEMENTARY		124		3	5.4
9088421	2018-11-16	3:00 pm	2018-11-19	8:00 am	73	GRANBERY ELEMENTARY		121		3	3.6
9088422	2018-11-16	3:00 pm	2018-11-19	8:00 am	71	GRANBERY ELEMENTARY		119		3	4.9
9088423	2018-11-16	3:00 pm	2018-11-19	8:00 am	74	GRANBERY ELEMENTARY		116		3	22.1
9088424	2018-11-16	3:00 pm	2018-11-19	8:00 am	73	GRANBERY ELEMENTARY		MAIN OFFICE		3	4.1
9088425	2018-11-16	3:00 pm	2018-11-19	8:00 am	74	GRANBERY ELEMENTARY		PRINCIPAL		3	4.4
9088426	2018-11-16	3:00 pm	2018-11-19	8:00 am	75	GRANBERY ELEMENTARY		NURSE		3	???

Radon test result report for:

GRANBERY ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9203165	107	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	1.3 ± 0.4	2019-07-29
9203161	116	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	4.5 ± 0.5	2019-07-29
9203162	119	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	0.9 ± 0.4	2019-07-29
9203163	124	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	4.1 ± 0.5	2019-07-29
9203164	125	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	1.4 ± 0.4	2019-07-29
9203166	MAIN OFFICE	2019-07-23 @ 9:00 am	2019-07-25 @ 10:00 am	1.8 ± 0.5	2019-07-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

CHURCH WELL ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217157	125	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	1.1 ± 0.2	2018-06-28
7217158	125	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	0.8 ± 0.2	2018-06-28
7217153	154	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	1.2 ± 0.2	2018-06-28
7217154	157	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	0.9 ± 0.2	2018-06-28
7217155	158	2018-06-25 @ 10:00 am	2018-06-27 @ 12:00 pm	0.8 ± 0.2	2018-06-28

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

JONES PAIDEIA MAGNET

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962661	101	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	6.7 ± 0.4	2017-12-22
7962663	102	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	8.5 ± 0.4	2017-12-22
7962657	104	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	1.4 ± 0.2	2017-12-22
7962658	107	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	5.6 ± 0.4	2017-12-22
7962659	107	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	4.9 ± 0.4	2017-12-22
7962655	11	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	8.9 ± 0.5	2017-12-22
7962654	13	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	4.3 ± 0.3	2017-12-22
7962656	GUIDANCE	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	132.0 ± 2.9	2017-12-22
7962664	MAIN OFFICE	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	14.8 ± 0.6	2017-12-22
7962662	MS. LANE	2017-12-19 @ 11:00 am	2017-12-21 @ 3:00 pm	4.1 ± 0.3	2017-12-22

Radon test result report for:

JONES PAIDEIA MAGNET

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962701	101	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	< 0.3	2018-04-06
7962702	102	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.6 ± 0.3	2018-04-06
7962704	104	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	0.9 ± 0.3	2018-04-06
7962703	104	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.1 ± 0.3	2018-04-06
7962705	107	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.2 ± 0.3	2018-04-06
7962706	11	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	3.5 ± 0.4	2018-04-06
7962709	12	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.6 ± 0.3	2018-04-06
7962708	15	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	3.0 ± 0.4	2018-04-06
7962707	COUNSELOR	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.2 ± 0.3	2018-04-06
7962711	MAIN OFFICE	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	2.8 ± 0.4	2018-04-06
7962710	PRINCIPAL&APOS;S OFFICE	2018-04-02 @ 3:00 pm	2018-04-04 @ 1:00 pm	1.5 ± 0.3	2018-04-06

Radon test result report for:
JOHN EARLY MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7065653	115	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	< 0.3	2017-10-17
7065646	117	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	< 0.3	2017-10-17
7065647	122	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.6 ± 0.3	2017-10-17
7065648	125	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.1 ± 0.3	2017-10-17
7065649	126	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.2 ± 0.3	2017-10-17
7065650	126	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.0 ± 0.2	2017-10-17
7065652	128	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.9 ± 0.3	2017-10-17
7065651	129	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	1.1 ± 0.3	2017-10-17
7065645	139	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	0.7 ± 0.2	2017-10-17
7065641	144	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	0.9 ± 0.2	2017-10-17
7065642	145	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	0.7 ± 0.2	2017-10-17
7065643	148	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	< 0.3	2017-10-17
7065644	149	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	0.9 ± 0.2	2017-10-17
7065654	LIBRARY	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	0.9 ± 0.2	2017-10-17
7065655	LIBRARY	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	< 0.3	2017-10-17
7065656	PRINCIPAL	2017-10-13 @ 3:00 pm	2017-10-16 @ 10:00 am	< 0.3	2017-10-17

Radon test result report for:
MCKISSACK MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962673	110	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	1.7 ± 0.3	2017-12-22
7962674	114	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	3.5 ± 0.3	2017-12-22
7962675	117	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	13.5 ± 0.6	2017-12-22
7962677	118	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	2.7 ± 0.3	2017-12-22
7962676	119	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	22.2 ± 0.8	2017-12-22
7962672	124	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	1.6 ± 0.3	2017-12-22
7962671	128	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	2.2 ± 0.2	2017-12-22
7962670	132	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	1.6 ± 0.2	2017-12-22
7962668	134	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	1.2 ± 0.2	2017-12-22
7962669	134	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	1.2 ± 0.2	2017-12-22
7962667	138	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	5.1 ± 0.4	2017-12-22
7962665	52	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	2.8 ± 0.3	2017-12-22
7962679	MAIN OFFICE	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	3.7 ± 0.3	2017-12-22
7962680	MAIN OFFICE	2017-12-19 @ 2:00 pm	2017-12-21 @ 4:00 pm	3.1 ± 0.3	2017-12-22

Radon test result report for:

MCKISSACK ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217186	114	2018-07-03 @ 11:00 am	2018-07-05 @ 1:00 pm	0.8 ± 0.2	2018-07-06
7217187	117	2018-07-03 @ 11:00 am	2018-07-05 @ 1:00 pm	1.7 ± 0.2	2018-07-06
7217188	119	2018-07-03 @ 11:00 am	2018-07-05 @ 1:00 pm	1.2 ± 0.2	2018-07-06
7217189	MAIN OFFICE	2018-07-03 @ 11:00 am	2018-07-05 @ 1:00 pm	4.7 ± 0.3	2018-07-06

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

January 10, 2019

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
MCKISSACK

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9127731	MAIN OFFICE	2018-12-27 @ 11:00 am	2018-12-31 @ 10:00 am	3.7 ± 0.4	2019-01-03
9127732	MAIN OFFICE	2018-12-27 @ 11:00 am	2018-12-31 @ 10:00 am	3.2 ± 0.4	2019-01-03

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

HULL JACKSON ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962412	140	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	2.1 ± 0.5	2017-12-26
7962413	170	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	1.9 ± 0.5	2017-12-26
7962416	220	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	3.5 ± 0.6	2017-12-26
7962417	230	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	2.1 ± 0.5	2017-12-26
7962418	260	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	2.8 ± 0.5	2017-12-26
7962419	260	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	3.1 ± 0.5	2017-12-26
7962415	350	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	4.3 ± 0.6	2017-12-26
7962420	9999	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	< 0.3	2017-12-26
7962421	COMPUTER LAB	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	1.9 ± 0.5	2017-12-26
7962414	INFANTS	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	4.6 ± 0.7	2017-12-26
7962422	MUSIC	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	1.3 ± 0.4	2017-12-26
7962423	OFFICE	2017-12-19 @ 11:00 am	2017-12-21 @ 10:00 am	1.9 ± 0.5	2017-12-26

Radon test result report for:
MCMURRAY MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9054851	109	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	1.2 ± 0.2	2018-07-18
9054850	111	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	1.5 ± 0.3	2018-07-18
9054849	112	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	0.8 ± 0.2	2018-07-18
9054848	115	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	1.4 ± 0.3	2018-07-18
9054852	121	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	< 0.3	2018-07-18
9054853	122	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	< 0.3	2018-07-18
9054854	126	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	< 0.3	2018-07-18
9054856	NEW OFFICE (BACK)	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	< 0.3	2018-07-18
9054855	NEW OFFICE (FRONT)	2018-07-13 @ 1:00 pm	2018-07-16 @ 1:00 pm	< 0.3	2018-07-18

Radon test result report for:
W. B. BASS

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962429	101	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	1.7 ± 0.5	2017-12-26
7962430	101	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.0 ± 0.5	2017-12-26
7962428	102	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.9 ± 0.6	2017-12-26
7962425	105	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.6 ± 0.5	2017-12-26
7962426	107	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	4.0 ± 0.7	2017-12-26
7962432	109	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.7 ± 0.5	2017-12-26
7962431	110	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.7 ± 0.6	2017-12-26
7962427	112	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.6 ± 0.6	2017-12-26
7962433	B101	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	4.5 ± 0.6	2017-12-26
7962434	B102	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	4.2 ± 0.6	2017-12-26
7962424	MUSIC	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	2.1 ± 0.5	2017-12-26
7962435	OFFICE	2017-12-19 @ 11:00 am	2017-12-21 @ 11:00 am	3.1 ± 0.6	2017-12-26

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
W A BASS MIDDLE

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217185	138	2018-07-03 @ 10:00 am	2018-07-05 @ 12:00 pm	1.1 ± 0.2	2018-07-06
7217184	B101	2018-07-03 @ 10:00 am	2018-07-05 @ 12:00 pm	0.7 ± 0.2	2018-07-06
7217183	B102	2018-07-03 @ 10:00 am	2018-07-05 @ 12:00 pm	0.6 ± 0.2	2018-07-06

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:**HUME FOGG HIGH SCHOOL**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962247	103	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.6 ± 0.2	2017-12-05
7962248	107	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	1.0 ± 0.2	2017-12-05
7962244	112	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.7 ± 0.2	2017-12-05
7962245	114	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.7 ± 0.2	2017-12-05
7962250	BAND ROOM	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.7 ± 0.2	2017-12-05
7962246	CAFETERIA	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	1.1 ± 0.2	2017-12-05
7962252	MAIN OFFICE	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	< 0.3	2017-12-05
7962253	MAIN OFFICE	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.7 ± 0.2	2017-12-05
7962257	PRINCIPAL OFFICE	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.5 ± 0.2	2017-12-05
7962249	THEATER ARTS	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.5 ± 0.2	2017-12-05
7962251	UPPER BAND ROOM	2017-12-01 @ 2:00 pm	2017-12-04 @ 8:00 am	0.9 ± 0.2	2017-12-05

Radon test result report for:
GOWER ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7962444	101	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.1 ± 0.4	2017-12-26
7962445	106	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	4.3 ± 0.6	2017-12-26
7962438	202	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.6 ± 0.5	2017-12-26
7962439	202	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.8 ± 0.6	2017-12-26
7962441	205	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	4.0 ± 0.6	2017-12-26
7962442	211	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.4 ± 0.5	2017-12-26
7962443	213	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	3.0 ± 0.5	2017-12-26
7962446	301	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	5.1 ± 0.6	2017-12-26
7962447	401	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.1 ± 0.5	2017-12-26
7962448	403	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	1.0 ± 0.4	2017-12-26
7962449	405	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	2.7 ± 0.5	2017-12-26
7962450	405	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	3.1 ± 0.5	2017-12-26
7962452	409	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	1.7 ± 0.4	2017-12-26
7962440	9999	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	< 0.3	2017-12-26
7962437	MEDIA CENTER	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	3.2 ± 0.5	2017-12-26
7962453	MUSIC	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	3.2 ± 0.5	2017-12-26
7962436	OFFICE	2017-12-19 @ 12:00 pm	2017-12-21 @ 12:00 pm	3.3 ± 0.5	2017-12-26

August 3, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
GOWER ELEMENTARY

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7217181	106	2018-07-03 @ 10:00 am	2018-07-05 @ 11:00 am	1.1 ± 0.2	2018-07-06
7217182	107	2018-07-03 @ 10:00 am	2018-07-05 @ 11:00 am	1.0 ± 0.2	2018-07-06
7217180	205	2018-07-03 @ 10:00 am	2018-07-05 @ 11:00 am	1.3 ± 0.2	2018-07-06
7217179	405	2018-07-03 @ 10:00 am	2018-07-05 @ 11:00 am	3.2 ± 0.3	2018-07-06

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498